



Boulder Circle/Virginia Cove:
1. Televisc culverts to determine condition. If condition is ok, repave pavement to reduce snow plowing concerns. If culvert is failing, replace.
2. Vehicle tracking and poor drainage on outside curve of Smithtown Road. Survey required.

Cajed Lane:
1. Televisc culvert to determine condition. If condition is ok, repave pavement to reduce snow plowing concerns. If culvert is failing, replace.

Fairway Dr/Ayrshire Ln:
1. Significant standing water at intersection and at cross walk. Likely requires removal of curb & sidewalk to repair. Survey required.

Star Lane:
1. Standing water at edge of pavement and off-tracking of vehicles increases issues. Area does not have clear path of drainage away from area. Survey will be required. Likely extend curb around radii.

Howards Point Road:
1. Standing water at edge of pavement and off-tracking of vehicles increases issues. Area does not have clear path of drainage away from pavement. Survey will be required. Likely extend curb around radii. Confirm design vehicle as Howards Point sees higher traffic and larger vehicles than short cul-de-sacs off of Smithtown Road.

Christopher Road:
1. Standing water at edge of pavement and off-tracking of vehicles increases issues. Area does not have clear path of drainage away from area. Survey will be required. Likely extend curb around radii.

Legend

- Project Locations
- Parcels
- City Limits

0 750 Feet

Source: City of Shorewood, Hennepin County, MN DOT

Map Document: \laeserver\GIS\SRV\Pro\2023\2024_Project_Overview_Maps\Shorewood_2024_Project_Overview_Maps\Shorewood_2024_Project_Overview_Maps.aprx | Username: Ben.Oman | Date Saved: 1/17/2024 10:22 AM